





IMAGE	ERROR	CAUSE	REMEDY
	<p>Bilateral radiopaque streaks</p>	<p>Large jaw size not selected to accommodate 3rd molars</p>	<p>Use large jaw size to bring 3rd molars away from the edge of the focal trough</p>
	<p>Radiopaque streaks on both sides</p> <p>Excessive one-sided overlap</p> <p>Notice teeth are different sizes on opposing sides</p>	<p>Midline not aligned with midsagittal laser</p>	<p>Verify dental arches and midline are aligned with mid-sagittal laser</p>
	<p>Radiopaque ghost image on left side</p> <p>Excessive one-sided overlap</p>	<p>Midsagittal plane misaligned</p> <p>Dental arches/Face slightly twisted</p>	<p>Verify dental arches and midline are aligned with mid-sagittal laser with no tilting or twisting</p>
	<p>Smile shape</p> <p>Bilateral radiopaque streaks</p> <p>Excessive overlap</p>	<p>Chin too low</p>	<p>Raise ProMax to bring occlusal plane parallel to the floor</p>
	<p>Frown shape</p> <p>Bilateral radiopaque ghost images</p> <p>Excessive overlap</p>	<p>Chin too high</p>	<p>Lower Imaging Unit to bring occlusal plane parallel to the floor</p>
	<p>Blurriness, radiopaque ghost images</p>	<p>Teeth not in grooves</p>	<p>Have patient bite in both grooves and reposition</p>

EDU008A.2019